

This is a two-story, frame side-gabled Dutch Colonial Revival style dwelling constructed ca. 1940. The dwelling has been extensively remodeled with added synthetic siding, bay windows, main façade porch, a hipped roof addition on the east façade and chimney.

To the rear of the dwelling is a ca. 1990 garage also **Noncontributing**.

