

207 W. Station Street – Contributing



ARC 05-10 – demolish existing detached garage and construct a new detached garage

This is a two- and one-half-story, frame rectangular American Foursquare dwelling built ca. 1896 with a hipped roof of asphalt shingles, an exterior brick chimney, a continuous foundation of rock-faced concrete block and an exterior of weatherboard siding on the first floor and wood shingles on the upper facade. On the main elevation is a one-story, partial-width, hipped roof porch with square wood columns. The columns rest on a solid frame wall with an exterior of wood shingles. The porch was added ca. 1920 and later enclosed ca. 1957 with four-light, aluminum hopper windows. The main entrance leads to the enclosed porch and retains its original, single-light glass and wood door. Windows on the dwelling are original, one-over-one double hung wood sash. On the main façade is a large, single-light window beneath a single-light rectangular transom with a wood surround. At the roofline of the main (N) façade is a gable roof wall dormer with a square, single-light attic window and an exterior of decorative weatherboarding with a sawtooth pattern.

To the rear is a dilapidated ca. 1925, one-bay, frame garage with an gable front roof of asphalt shingles, a weatherboard exterior and hinged double vertical board doors with cross braces. **Noncontributing**

